Work Order ID 102674

Quality Control

102674

Page 1

Monday, June 10, 20	13 9:53:19 AM		1(1)	/n/4						Page 1	•
Item ID: D32 Revision ID: Item Name: Pane			Accept	*N90	0040	1100)* s	Setup Sta	IVI	S1* S2*	
Start Date: 6/10 Required Date: 6/14 Reference:	/2013 Start Qty: 8.00 /2013 Req'd Qty: 8.00	*8* *8*		Cust Ite Custom					IV	. . 7	
Approvals: Pro	ocess Plan: MF	Date: (3-6 -)	Tooling: SPC (Y/N):	**	Date:		F	Run Sta	1/1	R1* R2*	
Sequence ID/ Work Center ID	Operation Description	-	Set Up/ Run Hours	Tool I	D Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr D3256	Revision Nbr									. †	
*100 *100* Waterjet FLOW CNC Waterjet 304.039	FLOW WATER JET Memo 1-Cut as po Dwg Rev: Prog Rev: 2-Deburr it	E	0.00				පි.	.0		JMB-	e-10
*110 * QC Quality Control	QC2- Inspect parts off i Memo	nachine FAI/FAIB	0.00				8	- O		JMB-	G~10
*120	QC8- Inspect parts - sec	cond check	0.00					\2 C\		OAS (
QC	Memo		0.00				<u>(8)</u>	13.06	10	Z.	

Work Order ID 102674 Monday, June 10, 2013 9:53:19 AM		•	*102674*							Page 2			
Item ID: Revision ID: Item Name:	D3256-1	· <u>.</u>	e e en en	Accept	*	N900	040	100)*	Setup Sta	1 /1	S1* S2*	
Start Date: Required Date Reference:	6/10/2013 e: 6/14/2013	Start Qty: 8.00 Req'd Qty: 8.00	*8* *8*			Cust Item I Customer:	ID:					1	
Approvals:	Process Pla	an: Date		Tooling: SPC (Y/N):			ate:			Run Sta	I/I	R1*	
Sequence ID/ Work Center 130 *130* Brake NC Brake NC	ID .	Operation Description NC BRAKE Memo Form using D3256-1	T2	Set Up/ Run Hour 0.00	s	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp FF 13-06-1	
140 *140 QC Quality Control		QC5- Inspect part completeness to	o step on W/O	0.00 5	G R	·			8				
150 *150* Packaging		Identify as per dwg & Stock Loca Memo	ation: <u>5T 1</u> 87	0.00			6	Ä.	8	X	Mill	I. 13-06-1	

Packaging

Work Order ID 102674 Monday, June 10, 2013 9:53:19 AM D3256-1 Item ID: Accept *N900040100* Setup Start **Revision ID:** Stop Item Name: Panel **Start Date:** Start Qty: 8.00 6/10/2013 **Cust Item ID: Required Date: 6/14/2013** Req'd Qty: 8.00 *8* **Customer:** Reference: Run Start **Process Plan: Approvals:** Date: **Tooling:** Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool# Tool ID Plan Reject Accept Reject Work Center ID Description **Run Hours** Qty Code Qty Number

0.00

0.00

QC21- Final Inspection - Work Order Release

Memo

160

QC

160

Quality Control

MCZ 13-06-12

13/6-10

Insp.

Stamp

Page 3

Picklist Print

Monday, June 10, 2013 9:53:16 AM

Work Order ID:

102674

Parent Item:

D3256-1

Parent Item Name:

Panel

Start Date: 6/10/2013

Required Date: 6/14/2013

Start Qty: 8.00


Required Qty: 8.00


Comments:

IPP Rev:A New Issue 07-09-28 EC verified by:DD

IPP Rev:b ECN 1052 07-10-31 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S22GA 304/316 .032 Sheet		Purchased	No			100	sf	181.4800	0.987	2.3115789 9.0		• •	Tm13-6-10
				Location		Loc Qty	Loc	c Code		-1,,0) (
				MAT020		181.48							1
				1182 1208		10.76 55.47							4
				1218		115.25			121	889			





DART AEROSPACE LTD	Work Order:	102/074
Description: Access Panel Assembly	Part Number:	D3256-1
Inspection Dwg: D3256 Rev: E		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
6.000	+/-0.010	6-003"	-		ν	Jemoi
6.825	+/-0.010	6828" 24.00"	-		V	
24.00	+/-0.010	24.00"	_		T	Jamus
11.250	+/-0.010	11. 752'	1		· v	Jemu6 Produtos
12.750	+/-0.010	12.754"	-		丁	
						·
					1	
					,	
						·
						
						,

	·		DAC -		
Measured by:	Jm	Audited by:	66 0	Preliminary Approval:	
Date:	13-6-10	Date:	13-06-10	Date:	

Rev	Date	Change	Revised by	Approved
A	07.11.23	New Issue P/O D3256-041	KJ/JLM	
В	08.09.04	Dimensions removed	KJ/DD	
С	12.05.14	Dimensions updated per Dwg Rev D	KJ , N	
D	13.05.08	Dimensions updated per Dwg Rev E	KJ 🗚	